

SSO Maintenance Report

Date of Occurance	Address	Blockage Reason 1	Blockage Reason 2	Volume/Gallons	Responsibility	Removal Method	Receiving Waters	Mitigation Used on Untreated Waters	Actions to mitigate future SSO
04/03/14	Lift Station #5 & Lift Station #2 failed			30,000	Village	By-pass pump to Storm	Cal Union Ditch		
05/12/14	18610 Ashland	Rain		25	Village	Sewer Jet			Line maintenance
05/15/14	17620 Hillside	Undetermined		25	Village	Sewer Jet			Line maintenance